

Liquifilm®

WATER SOLUBLE PURGE FILM AND ADHESIVE



THE TRANSPARENT & FLEXIBLE PURGE GAS BARRIER FOR TIG WELDING





CLEANClean pipe.

AVAILABLE IN BRICK & KIT FORMATS



Kit Contents:

- · Liquifilm® Water Soluble Film Wound on Core
- Two 250 ml Bottles of Liquifilm® Water Soluble Adhesive
- · Cutting Knife
- Instruction Sheet





APPLY

Apply Liquifilm® Water Soluble Adhesive to inside of pipe.





CUT

Cut Liquifilm® in a circle 1.3 times greater than pipe diameter.





PRESS

Press glossy surface of Liquifilm® to tacky adhesive inside pipe.



Liquifilm®

WATER SOLUBLE PURGE FILM AND ADHESIVE



Impenetrable Purge Barrier

• Excellent Barrier for Retaining Noble Gas (Argon or Argon/Helium Mix)

Flexible & Robust

- For Use on Stainless, Duplex and Chromium Steels & Titanium Alloys
- Can Be Punctured for Gas Inlets and Outlets with Little Risk of Tearing
- High Resistance to Pressure, Allowing for Greater Positive Pressure to be Maintained in Weld Area

Impenetrable Purge Barrier

• For Ease of Viewing During Welding Process

Ease of Removal

- · Rapidly Dissolves in Hot or Cold Water
- Leaves No Residue In The Pipeline

Safe

• Suitable for Nuclear, Aerospace, and Other Applications

SPECIFICATIONS FOR LIQUIFILM® WATER SOLUBLE PURGE FILM AND ADHESIVE

LiquiFilm® Types and Sizes

PRODUCT	ITEM NO.	DESCRIPTION	DIMENSIONS		CASE
			ENGLISH	METRIC	PACK
Liquipum	ASWF-1/20RG	Liquifilm® Water Soluble Film Kit	39" x 65'	1 m x 20 m	12
Liquipus	ASWF-1/20B	Liquifilm® Water Soluble Film Brick Format	39" x 65'	1 m x 20 m	12
	AWSG-500	Liquifilm® Water Soluble Adhesive	16 fl oz	500 ml/bottle	24
9	AWSG-250	Liquifilm® Water Soluble Adhesive	8 fl oz	250 ml/bottle	48

For additional product information, quotations and ordering, please contact:

Aquasol Corporation

80 Thompson Street N. Tonawanda, NY 14120 USA

Toll Free: 1.800.564.WELD (9353) Phone: 716.564.8888

Fax: 716.564.8889

Email: info@aquasolcorporation.com aquasolwelding.com

Distributed By:



